


FIGURES

LIST OF FIGURES

- Figure 1. Site Location Map
- Figure 2. IEL Site w/Monitoring Well Network
- Figure 3. 1997 Photograph of the IEL Site
- Figure 4. 1997 Photograph with Site Fence and Site Boundary Noted
- Figure 5. August 2000 Photograph of the IEL Site
- Figure 6. August 2000 Photograph with Site Fence and Site Boundary Noted
- Figure 7. 1991 Color Infrared Photo of the IEL Site
- Figure 8. 1991 Color Infrared Photo with Site Fence and Site Boundary Noted
- Figure 9. August 2000 Color Infrared Photograph of the IEL Site
- Figure 10. August 2000 Color Infrared Photo with Site Fence and Site Boundary Noted
- Figure 11. IEL Site Conditions, July, 31, 2003
- Figure 12. Conceptual Rotation Mowing Program
- Figure 13. Conceptual Forested Island
- Figure 14. Current (August 2000) Ecological Regimes (Figure 1 from Petition)
- Figure 15. Proposed Tree Planting Area (Figure 2 from Petition)
- Figure 16. Future Ecological Regimes (Figure 3 from Petition)
- Figure A2. IEL Monitoring Wells, Well Designation & Completion Depth
- Figure 17. IEL Site Map w/Current Monitoring Well Network
- Figure 18. Uppermost Continuous Groundwater Unit Potentiometric Map
- Figure 19. Post-2003 IEL Monitoring Well Network
- Figure 20. IEL Remedial Implementation Schedule
- Figure A3. Industrial Excess Landfill Revised Monitoring Well Network



SHARP
AND ASSOCIATES, INC.
982 CRUPPER AVE.
COLUMBUS, OHIO 43229
(614) 841-4650 / FAX (614) 841-4660

SITE LOCATION MAP

INDUSTRIAL EXCESS LANDFILL
UNIONTOWN, OHIO

FIGURE


1


PROJECT NUMBER
2101

DATE
08/15/03

FILE NAME
2101/FIG.1

SCALE
N.T.S.





SHARP
AND ASSOCIATES, INC.
982 CRUPPER AVE.
COLUMBUS, OHIO 43229
(614) 841-4650 / FAX (614) 841-4660

1997 PHOTOGRAPH OF THE IEL SITE

**INDUSTRIAL EXCESS LANDFILL
UNIONTOWN, OHIO**

PROJECT NUMBER
2101


DATE
08/15/03

FILE NAME
2101/FIG.3

SCALE
N.T.S.

FIGURE

3



SHARP
AND ASSOCIATES, INC.
982 CRUPPER AVE
COLUMBUS, OHIO 43229
(614) 841-4650 / FAX (614) 841-4660

1997 PHOTOGRAPH WITH SITE FENCE AND SITE BOUNDARY NOTED

**INDUSTRIAL EXCESS LANDFILL
UNIONTOWN, OHIO**

PROJECT NUMBER
2101


DATE
08/15/03

FILE NAME
2101/FIG.4

SCALE
N.T.S.

FIGURE

4



SHARP
AND ASSOCIATES, INC.
982 CRUPPER AVE
COLUMBUS, OHIO 43229
(614) 841-4650 / FAX (614) 841-4660

AUGUST 2000 PHOTOGRAPH OF THE IEL SITE

INDUSTRIAL EXCESS LANDFILL
UNIONTOWN, OHIO

PROJECT NUMBER
2101

DATE
08/15/03

FILE NAME
2101/FIG.5

SCALE
N.T.S.

FIGURE

5



SHARP
AND ASSOCIATES, INC.
982 CRUPPER AVE
COLUMBUS, OHIO 43229
(614) 841-4650 / FAX (614) 841-4660

AUGUST 2000 PHOTOGRAPH WITH SITE FENCE AND SITE BOUNDARY NOTED

INDUSTRIAL EXCESS LANDFILL
UNIONTOWN, OHIO

PROJECT NUMBER	DATE	FILE NAME	SCALE
2101	08/15/03	2101/FIG.6	N.T.S.

FIGURE

6



SHARP
AND ASSOCIATES, INC.
982 CRUPPER AVE
COLUMBUS, OHIO 43229
(614) 841-4650 / FAX (614) 841-4660

1991 COLOR INFRARED PHOTO OF IEL SITE

INDUSTRIAL EXCESS LANDFILL
UNIONTOWN, OHIO

PROJECT NUMBER
2101


DATE
08/15/03

FILE NAME
2101/FIG.7

SCALE
N.T.S.

FIGURE

7



SHARP
AND ASSOCIATES, INC.
982 CRUPPER AVE
COLUMBUS, OHIO 43229
(614) 841-4650 / FAX (614) 841-4660

1991 COLOR INFRARED PHOTO WITH SITE FENCE AND SITE BOUNDARY NOTED

INDUSTRIAL EXCESS LANDFILL
UNIONTOWN, OHIO

FIGURE


8

PROJECT NUMBER
2101

DATE
08/15/03

FILE NAME
2101/FIG.8

SCALE
N.T.S.



SHARP
AND ASSOCIATES, INC.
982 CRUPPER AVE
COLUMBUS, OHIO 43229
(614) 841-4660 / FAX (614) 841-4660

AUGUST 2000 COLOR INFRARED PHOTOGRAPH OF THE IEL SITE

**INDUSTRIAL EXCESS LANDFILL
UNIONTOWN, OHIO**

FIGURE

9

PROJECT NUMBER
2101

DATE
08/15/03

FILE NAME
2101/FIG.9

SCALE
N.T.S.



SHARP
AND ASSOCIATES, INC.
983 CRUPPER AVE.
COLUMBUS, OHIO 43229
(614) 841-4650 / FAX (614) 841-4660

AUGUST 2000 COLOR INFRARED PHOTO WITH SITE FENCE AND SITE BOUNDARY

INDUSTRIAL EXCESS LANDFILL
UNIONTOWN, OHIO

FIGURE

10

PROJECT NUMBER
2101

DATE
08/15/03

FILE NAME
2101/FIG.10

SCALE
N.T.S.